

US009409266B2

(12) United States Patent

Buldtmann et al.

(54) METHOD AND DEVICE FOR CHANGING A FRONT SEAL PLATE IN AN AIRCRAFT ENGINE

(75) Inventors: Markus Buldtmann, Ahlerstedt (DE);

Alexander Hinz, Ratekau (DE); Eugen Roppelt, Hamburg (DE); Jens Fitter,

Hamburg (DE)

(73) Assignee: LUFTHANSA TECHNIK AG,

Hamburg (DE)

(*) Notice: Subject to any disclaimer, the term of this

patent is extended or adjusted under 35

U.S.C. 154(b) by 293 days.

(21) Appl. No.: 13/982,445

(22) PCT Filed: Jan. 24, 2012

(86) PCT No.: PCT/EP2012/000297

§ 371 (c)(1),

(2), (4) Date: Oct. 18, 2013

(87) PCT Pub. No.: WO2012/100933

PCT Pub. Date: Aug. 2, 2012

(65) **Prior Publication Data**

US 2014/0130352 A1 May 15, 2014

(30) Foreign Application Priority Data

Jan. 28, 2011 (DE) 10 2011 009 770

(51) **Int. Cl.**

B23P 19/04 (2006.01) **B23P 6/00** (2006.01) **F01D 25/28** (2006.01)

(52) U.S. Cl.

 (10) Patent No.: US 9,409,266 B2

(45) **Date of Patent:**

Aug. 9, 2016

(2013.01); F05D 2240/55 (2013.01); Y10T 29/4973 (2015.01); Y10T 29/49297 (2015.01); (Continued)

(58) Field of Classification Search

CPC B23P 6/002; B23P 6/005; B23P 19/027; B23P 19/042; F01D 11/00; F01D 11/003; F01D 11/005; F01D 25/16; F01D 25/285; F05D 2230/60; F05D 2230/70; F05D 2230/72; F05D 2230/80; F05D 2240/54; F05D 2240/55; Y10T 29/49318; Y10T 29/4932; Y10T 29/49719; Y10T 29/49721; Y10T 29/49723; Y10T 29/4973; Y10T 29/4973; Y10T 29/49822

See application file for complete search history.

(56) References Cited

U.S. PATENT DOCUMENTS

4,200,273 A 4/1980 Das Gupta et al. 4,685,286 A 8/1987 Hetzer et al. (Continued)

FOREIGN PATENT DOCUMENTS

DE 1 086 950 8/1960 DE 196 43 336 4/1998 (Continued)

Primary Examiner — Ryan J Walters
Assistant Examiner — Matthew P Travers

(74) Attorney, Agent, or Firm — Saliwanchik, Lloyd & Eisenschenk

(57) ABSTRACT

Method for removing a front seal plate from an aircraft engine, the method comprising at least the following steps:

- a) separating a part engine unit from the aircraft engine, the part engine unit comprising the core engine and the low-pressure turbine of the aircraft engine,
- b) removing a front seal plate nut from the part engine unit,
- c) removing the front seal plate from the part engine unit.

8 Claims, 3 Drawing Sheets

